

**Flood Control Project Maintenance**  
**2012 Structure Summary Report**  
**Overall Unit and Item Ratings**

## San Joaquin County Flood Control and Water Conservation District

### Duck Creek Diversion Weir And Control Structure

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments	A
	Encroachments	A
	Culverts: Inlets / Outlets	A
	Culverts: Breaks / Holes / Cracks	A
	Metal Pipes	A
	Trash Racks	N
	Flap Gates	N
	Sluice/Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Concrete Surfaces	A
	Concrete Tilting / Settlement	A
	Concrete Foundations	A
	Security Fencing	N
	Closure Structures	N
	Trash Rakes	N
	Other Metallic Items	A
	Monolith Joints	A
	Safety	A

### Mormon Slough Pumping Plant No. 1

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	A
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	N
	Security Fencing	M
	Intake and Discharge Pipes	A

**Flood Control Project Maintenance****2012 Structure Summary Report****Overall Unit and Item Ratings****San Joaquin County Flood Control and Water Conservation District (cont.)****Mormon Slough Pumping Plant No. 2**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	A
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	M
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	A
	Security Fencing	A
	Intake and Discharge Pipes	A

**Mormon Slough Pumping Plant No. 3**

Overall Unit Rating	Rated Item	Item Rating
<b>A</b>	Operating Log	A
	Operation & Maintenance Manual	A
	Plant Building	A
	Communications	A
	Safety	A
	Cranes	N
	Pumps	A
	Power	A
	Motors, Engines, Fans & Gear Reducers	A
	Pump Control Systems	A
	Sumps/Wet Well	A
	Trash Racks	A
	Trash Rakes	N
	Sluice / Slide Gates	A
	Electric Gate Operators	N
	Manual Gate Operators	A
	Other Metallic Items	A
	Flap Gates	A
	Closure Structures	N
	Security Fencing	A
	Intake and Discharge Pipes	A

**Flood Control Project Maintenance****Unit Cover Sheet****2012 Structure Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Structure
Duck Creek Diversion Weir And Control Structure

Structure Rating	<a href="#">A</a>
Date of Inspection	<a href="#">7/10/2012</a>
DWR Inspector	<a href="#">Pavel Kazi</a>
Accompanied By	<a href="#">Jim Caruso</a> <a href="#">SJCF&amp;WCD</a>
	<a href="#">Jay Jauregui</a>

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure							07/10/2012 07/10/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Structures	Vegetation & Obstructions		A	Inspector Comments: There was minimal vegetation around the structure. The flow was not impeded.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	2 Y
2	0.00	0.00	Structures	Shoaling / Sedimentation		A	Inspector Comments: No shoaling or sediment was present.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	3
3	0.00	0.00	Structures	Erosion / Bank Caving		A	Inspector Comments: No erosion or bank caving was observed on the side of the levee.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	4
4	0.00	0.00	Structures	Revetments		A	Inspector Comments: Existing riprap protection was properly maintained.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	5 Y
5	0.00	0.00	Structures	Encroachments		A	Inspector Comments: No trash or debris was found around the structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	6
6	0.00	0.00	Structures	Culverts: Inlets / Outlets		A	Inspector Comments: The culvert's inlet and outlet were free of any debris.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	7 Y
7	0.00	0.00	Structures	Culverts: Breaks / Holes / Cracks		A	Inspector Comments: No visible cracks or holes were found that would result in significant water leakage in the culvert.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	8
8	0.00	0.00	Structures	Metal Pipes		A	Inspector Comments: The corrugated pipes inside the culvert appeared to be in good condition.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	9
9	0.00	0.00	Structures	Trash Racks		N	Inspector Comments: This item does not apply to this inspection.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	10
10	0.00	0.00	Structures	Flap Gates		N	Inspector Comments: No flap gates were present at this structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	11
11	0.00	0.00	Structures	Sluice/Slide Gates		A	Inspector Comments: The gates appeared to be in good working condition.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	12
12	0.00	0.00	Structures	Electric Gate Operators		N	Inspector Comments: No electric gate operator was found at this structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	13
13	0.00	0.00	Structures	Manual Gate Operators		A	Inspector Comments: The manual gate appeared to be operational.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	14 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure							07/10/2012 07/10/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
14	0.00	0.00	Structures	Concrete Surfaces		A	Inspector Comments: The concrete surfaces had minor cracking and the surface was weathered but they didn't pose any threats to the integrity of the structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	15 Y
15	0.00	0.00	Structures	Concrete Tilting / Settlement		A	Inspector Comments: No visible sliding or settlement was found on the structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	16
16	0.00	0.00	Structures	Concrete Foundations		A	Inspector Comments: No souring or erosion was found near the structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	17
17	0.00	0.00	Structures	Security Fencing		N	Inspector Comments: No security fence was found in this structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	18
18	0.00	0.00	Structures	Closure Structures		N	Inspector Comments: This item does not apply to this inspection.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	19
19	0.00	0.00	Structures	Trash Rakes		N	Inspector Comments: Trash rakes don't exist on this structure.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	20
20	0.00	0.00	Structures	Other Metallic Items		A	Inspector Comments: All metal parts appeared to be in good condition.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	21
21	0.00	0.00	Structures	Monolith Joints		A	Inspector Comments: All the monolith joint materials appeared to be in good condition.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	22
22	0.00	0.00	Structures	Safety		A	Inspector Comments: The wood railing top of the culvert appeared to provide adequate protection against fall hazards.	37.938383 ° -120.990133 °	37.938383 ° -120.990133 °	23 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		07/10/2012 07/10/2012	Pavel Kazi

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Vegetation & Obstructions

View of the vegetation at the control structure.

pkazi\_t\_20120810\_170.jpg



Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Revetments

View of the revetments looking upstream.

pkazi\_t\_20120810\_165.jpg



Levee Mile Report Line	4
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Revetments

View of the revetments looking downstream.

pkazi\_t\_20120810\_166.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		07/10/2012 07/10/2012	Pavel Kazi

Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Culverts: Inlets / Outlets
View of the culvert outlet.	
pkazi_t_20120810_167.jpg	



Levee Mile Report Line	6
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Culverts: Inlets / Outlets
View of the culvert inlet.	
pkazi_t_20120810_168.jpg	



Levee Mile Report Line	13
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Manual Gate Operators
View of the manual gate.	
pkazi_t_20120810_169.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Duck Creek Diversion Weir And Control Structure		07/10/2012 07/10/2012	Pavel Kazi

Levee Mile Report Line	14
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Concrete Surfaces

View of the weir.

pkazi\_t\_20120810\_171.jpg



Levee Mile Report Line	22
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Structures
Item	Safety

View of the railing top of the culvert.

pkazi\_t\_20120810\_172.jpg

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance****Unit Cover Sheet****2012 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 1

Pumping Plant Rating	<b>A</b>
Date of Inspection	7/17/2012
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCF&WCD
	Jay Jauregui SJCF

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1							07/17/2012 07/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Pump Stations	Operating Log		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Operating log was maintained and present at the pumping plant.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	1 Y
2	0.00	0.00	Pump Stations	Operation & Maintenance Manual		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The O&M manual was located next to the operating log.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	2 Y
3	0.00	0.00	Pump Stations	Plant Building		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The plant building was in good structural condition but there were lot of graffiti markings around the building.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	3 Y
4	0.00	0.00	Pump Stations	Communications		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: District personnel carry cell phones for communication.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	4
5	0.00	0.00	Pump Stations	Safety		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: There were no safety hazards found around the structure and the guard rails around the structure were in good condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	5 Y
6	0.00	0.00	Pump Stations	Cranes		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: No crane was present at this plant.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	6
7	0.00	0.00	Pump Stations	Pumps		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: All pumps were appeared to be in working condition and they were maintained, lubricated and tested periodically.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	7 Y
8	0.00	0.00	Pump Stations	Power		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The power source appeared to be safe and reliable.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	8
9	0.00	0.00	Pump Stations	Motors, Engines, Fans & Gear Reducers		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The vent fan was operational.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	10
10	0.00	0.00	Pump Stations	Pump Control Systems		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pump control systems were maintained properly and appeared to be free of damage.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	11

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1							07/17/2012 07/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
11	0.00	0.00	Pump Stations	Sumps/Wet Well		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The wet well was completely dry and very little debris was present during inspection.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	12 Y
12	0.00	0.00	Pump Stations	Trash Racks		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Trash racks were properly maintained and clear of debris.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	13 Y
13	0.00	0.00	Pump Stations	Trash Rakes		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Trash rakes don't exist at this plant.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	14
14	0.00	0.00	Pump Stations	Sluice / Slide Gates		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The slide gate appeared to be in good condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	15 Y
15	0.00	0.00	Pump Stations	Electric Gate Operators		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The Item does not apply to the pumping plant.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	16
16	0.00	0.00	Pump Stations	Manual Gate Operators		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Manual gate operator was in good operational condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	17 Y
17	0.00	0.00	Pump Stations	Other Metallic Items		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: All metal parts appeared to be in good condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	18
18	0.00	0.00	Pump Stations	Flap Gates		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The flap gates appeared to be in good working condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	19 Y
19	0.00	0.00	Pump Stations	Closure Structures		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: No closure structure was present at this plant.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	20
20	0.00	0.00	Pump Stations	Security Fencing		M	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Security fencing around the plant was damaged due to theft and vandalism.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	21
21	0.00	0.00	Pump Stations	Intake and Discharge Pipes		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pipes appeared to be in good working condition.	37.989633 ° -121.266933 °	37.989633 ° -121.266933 °	22

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Operating Log

View of the operation log in the plant.

pkazi\_t\_20120724\_128.jpg



Levee Mile Report Line	2
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Operation & Maintenance Manual

View of the O&M manual inside the plant.

pkazi\_t\_20120724\_129.jpg



Levee Mile Report Line	3
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Plant Building

View of the pumping plant.

pkazi\_t\_20120724\_130.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	5
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Safety

View of the guard rails around the plant.

pkazi\_t\_20120724\_131.jpg



Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of one of the pumps inside the plant.

pkazi\_t\_20120724\_132.jpg



Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of a pump inside the plant.

pkazi\_t\_20120724\_133.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sumps/Wet Well

View of the well which was completely dry.

pkazi\_t\_20120724\_134.jpg



Levee Mile Report Line	12
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Trash Racks

View of the trash racks.

pkazi\_t\_20120724\_135.jpg



Levee Mile Report Line	14
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sluice / Slide Gates

View of the slide gate well. The bottom well was free of debris.

pkazi\_t\_20120724\_136.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 1		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Manual Gate Operators
View of the manual gate.	
pkazi_t_20120724_137.jpg	



Levee Mile Report Line	18
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Flap Gates
View of the flap gates.	
pkazi_t_20120724_138.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance****Unit Cover Sheet****2012 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 2

Pumping Plant Rating	<b>A</b>
Date of Inspection	7/17/2012
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCF&WCD
	Jay Jauregui SJCF

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2							07/17/2012 07/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Pump Stations	Operating Log		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Operational log was present at the pump station.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	1 Y
2	0.00	0.00	Pump Stations	Operation & Maintenance Manual		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: O&M manual was found at the plant next to the operating log during the inspection.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	2
3	0.00	0.00	Pump Stations	Plant Building		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The plant building was in good structural condition without any major cracks in the concrete.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	3 Y
4	0.00	0.00	Pump Stations	Communications		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: District personnel carry cell phones.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	4
5	0.00	0.00	Pump Stations	Safety		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: No safety hazard was found around the structure. All hand rails were in working condition.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	5 Y
6	0.00	0.00	Pump Stations	Cranes		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: No crane exists at this plant.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	6
7	0.00	0.00	Pump Stations	Pumps		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pumps appeared to be well maintained and lubricated properly and the pumping system was tested periodically.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	7 Y
8	0.00	0.00	Pump Stations	Power		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The power source appeared to be safe and reliable.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	8
9	0.00	0.00	Pump Stations	Motors, Engines, Fans & Gear Reducers		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The vent fan was operational during the inspection.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	10
10	0.00	0.00	Pump Stations	Pump Control Systems		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pump control system was maintained to be free of corrosion or any damage.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	11 Y
11	0.00	0.00	Pump Stations	Sumps/Wet Well		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The wet well appeared to be clear of excessive debris or sediments.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	12 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2							07/17/2012 07/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
12	0.00	0.00	Pump Stations	Trash Racks		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Trash racks were properly maintained and free of any debris.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	13 Y
13	0.00	0.00	Pump Stations	Trash Rakes		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Trash rakes are not installed in this facility.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	14
14	0.00	0.00	Pump Stations	Sluice / Slide Gates		M	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The slide gate appeared to be operational but an encroachment was found bottom of the gate.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	15 Y
15	0.00	0.00	Pump Stations	Electric Gate Operators		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: This item was not present at this location.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	16
16	0.00	0.00	Pump Stations	Manual Gate Operators		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Manual gate operator appeared to be in good condition.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	17 Y
17	0.00	0.00	Pump Stations	Other Metallic Items		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: All the metal parts appeared to be in good condition.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	18
18	0.00	0.00	Pump Stations	Flap Gates		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Flap gates were in good condition and showed no damage.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	19 Y
19	0.00	0.00	Pump Stations	Closure Structures		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The closure structure appeared to be in good condition.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	20
20	0.00	0.00	Pump Stations	Security Fencing		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Security fencing was in good condition without any damage.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	21
21	0.00	0.00	Pump Stations	Intake and Discharge Pipes		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pipes had no break, holes or cracks.	37.982317 ° -121.249433 °	37.982317 ° -121.249433 °	22

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Operating Log

View of the operation log and O&M manual inside the pumping plant.

pkazi\_t\_20120720\_115.jpg



Levee Mile Report Line	3
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Plant Building

View of the pumping plant.

pkazi\_t\_20120720\_116.jpg



Levee Mile Report Line	5
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Safety

View of the hand rails around the pumping plant.

pkazi\_t\_20120720\_117.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of one of the pumps.

pkazi\_t\_20120720\_120.jpg



Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of another pump.

pkazi\_t\_20120720\_121.jpg



Levee Mile Report Line	10
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pump Control Systems

View of the power control system.

pkazi\_t\_20120720\_122.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**


**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sumps/Wet Well

View of the wet well.

pkazi\_t\_20120720\_123.jpg



Levee Mile Report Line	12
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Trash Racks

View of the trash racks.

pkazi\_t\_20120720\_124.jpg



Levee Mile Report Line	14
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sluice / Slide Gates

View of encroachment bottom of the slide gate.

pkazi\_t\_20120720\_125.jpg

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 2		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	16
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Manual Gate Operators

View of the manual gate.

pkazi\_t\_20120720\_126.jpg



Levee Mile Report Line	18
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Flap Gates

View of the flap gates on the waterside.

pkazi\_t\_20120720\_127.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance****Unit Cover Sheet****2012 Pumping Plant Inspection Results****San Joaquin County Flood Control and Water Conservation District**

Pumping Plant
Mormon Slough Pumping Plant No. 3

Pumping Plant Rating	<b>A</b>
Date of Inspection	7/17/2012
DWR Inspector	Pavel Kazi
Accompanied By	Jim Caruso SJCF&WCD
	Jay Jauregui SJCF

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure						Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3							07/17/2012 07/17/2012	Pavel Kazi

LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1	0.00	0.00	Pump Stations	Operating Log		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Maintenance log was present at the pumping plant.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	1 Y
2	0.00	0.00	Pump Stations	Operation & Maintenance Manual		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The O&M manual was present at the pumping plant next to the operating log.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	2
3	0.00	0.00	Pump Stations	Plant Building		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The plant building appeared to be in good structural condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	3 Y
4	0.00	0.00	Pump Stations	Communications		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The district personnel carry cell phones.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	4
5	0.00	0.00	Pump Stations	Safety		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: No safety hazard was found around the pumping plant and guard rails around the plant were in a good condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	5 Y
6	0.00	0.00	Pump Stations	Cranes		N	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: There are no cranes in this plant.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	6
7	0.00	0.00	Pump Stations	Pumps		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: All pumps were appeared to be in good condition and maintained properly.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	7 Y
8	0.00	0.00	Pump Stations	Power		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The power source appeared to be safe and reliable.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	8
9	0.00	0.00	Pump Stations	Motors, Engines, Fans & Gear Reducers		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Pumping motors appeared to be operational and lubrication was maintained on all the pumps.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	10
10	0.00	0.00	Pump Stations	Pump Control Systems		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The pump control system appeared to be operational and free of damage.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	11 Y
11	0.00	0.00	Pump Stations	Sumps/Wet Well		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Wet well was clear of any excessive debris.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	12 Y

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure							Structure Length	Inspection Start/End		Inspector	
Mormon Slough Pumping Plant No. 3								07/17/2012 07/17/2012		Pavel Kazi	
LMR No.	Levee Mile		Category	Item	Location *	Rating **	Action/Comment	GPS Latitude/Longitude		Issue No.	
	Start	End						Start	End	Photo	
12	0.00	0.00	Pump Stations	Trash Racks		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: The trash racks were free of any debris.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	13 Y	
13	0.00	0.00	Pump Stations	Trash Rakes		N	Item inspected visually only. Item was not operated during the inspection.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	14	
14	0.00	0.00	Pump Stations	Sluice / Slide Gates		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Slide gates appeared to be free of sediment and obstructions.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	15 Y	
15	0.00	0.00	Pump Stations	Electric Gate Operators		N	Item inspected visually only. Item was not operated during the inspection.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	16	
16	0.00	0.00	Pump Stations	Manual Gate Operators		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Manual gate appeared to be in good working condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	17	
17	0.00	0.00	Pump Stations	Other Metallic Items		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Other metallic parts within the pumping plant appeared to be in a good condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	18	
18	0.00	0.00	Pump Stations	Flap Gates		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Flap gates were appeared to be in good condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	19	
19	0.00	0.00	Pump Stations	Closure Structures		N	Item inspected visually only. Item was not operated during the inspection.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	20	
20	0.00	0.00	Pump Stations	Security Fencing		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Security fencing was undamaged and prevented unauthorized access.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	21 Y	
21	0.00	0.00	Pump Stations	Intake and Discharge Pipes		A	Item inspected visually only. Item was not operated during the inspection. Inspector Comments: Pipes appeared to be in good condition.	37.973983 ° -121.229967 °	37.973983 ° -121.229967 °	22	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment  
C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	1
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Operating Log

View of the operating log and O&M manual inside the pumping plant.

pkazi\_t\_20120720\_105.jpg



Levee Mile Report Line	3
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Plant Building

View of the pumping plant.

pkazi\_t\_20120720\_115.jpg



Levee Mile Report Line	5
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Safety

View of the guard rails around the plant.

pkazi\_t\_20120720\_116.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of one of the pumps.

pkazi\_t\_20120720\_108.jpg



Levee Mile Report Line	7
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pumps

View of another pump inside the pumping plant.

pkazi\_t\_20120720\_109.jpg



Levee Mile Report Line	10
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Pump Control Systems

View of the power control systems inside the plant.

pkazi\_t\_20120720\_110.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	11
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sumps/Wet Well

View of wet well.

pkazi\_t\_20120720\_111.jpg



Levee Mile Report Line	12
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Trash Racks

View of the trash racks.

pkazi\_t\_20120720\_117.jpg



Levee Mile Report Line	14
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Sluice / Slide Gates

View of the slide gate.

pkazi\_t\_20120720\_113.jpg

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Structure 2012**

**San Joaquin County Flood Control and Water Conservation District**

Structure	Structure Length	Inspection Start/End	Inspector
Mormon Slough Pumping Plant No. 3		07/17/2012 07/17/2012	Pavel Kazi

Levee Mile Report Line	20
Start Levee Mile	0.00
End Levee Mile	0.00
Location	
Category	Pump Stations
Item	Security Fencing
View of the security fencing around the pumping plant.	
pkazi_t_20120720_114.jpg	

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable

PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected, see Inspector Comment

C : Corrected